

Challenges of Protecting and Restoring a Groundwater - Dependent Prairie Stream: Iron Springs Creek, Southeastern North Dakota

Phil Gerla

*Midwest Groundwater Conference 2012
Groundwater Opportunities and Conflicts in the 21st Century:
Economy to Ecology*




Some Key Background Points –

1. Groundwater dependent (GWD) streams often have exceptional ecological, aesthetic, and recreational value
2. Management of GWD streams cannot be complete without considering surface water – groundwater interaction
3. Different regulatory and best-management practices may be needed for protecting the integrity and function of GWD streams

Sheyenne Delta of southeastern North Dakota hosts a few unique groundwater-dependent streams and wetlands

Purpose of the presentation – Case study that demonstrates how drainage mismanagement irreversibly damaged Iron Springs Creek



Why these few seeps and streams are important –

Wetland / dune habitat – western prairie fringed orchid

Drought-resistant woods and prairie


Host relic ice-age plants

Endemic fish and unusual macroinvertebrates

Groundwater storage and release moderates downstream flow




Iron Springs – former headwaters for a 6-km groundwater-dependent stream





Iron Transport in Circumneutral Groundwater



8 November 1906

Iron Springs Drain No. 10.

Notice of assessments, Review of assessments and letting of Contract

State of North Dakota, } ss. County of Richland, } Before the Board of County, Drain Commissioners. In the Matter of the Es- tablishment of a Drain in Freeman, and Shey- enne Townships, } Richland County, }		Sec. 20, Twp. 134, Range 52.		
		Ne¼	.01572	164 degrees 46 minutes 30 seconds
		Nw¼	.01572	E. a distance of 448.90 feet to the
		Sw¼	.01572	north and south quarter line of
		Se¼	.01572	said section, thence north follow-
				ing said quarter line a distance of
		Sec. 21, Twp. 134, Range 52.		5017.65 feet, thence at an angle of
		Ne¼	.00945	157 degrees 51 minutes 30 seconds E.
		Nw¼	.01572	a distance of 720 feet, thence at an
		Sw¼	.01258	angle of 156 degrees 37 min. 30 sec. W.
Assess- ment on, Account				



What were the consequences to Iron Springs and Iron Springs Creek?


incision since excavation of Ditch 10



3.2 m



08/08/2012



1 km upstream: weir and gauge at the crossing, installed circa 2000




same location in 2012; sheet pile washed out in 2011

former top of sheet pile


08/08/2012




2.5 km upstream at the head of incision




08/08/2012




National Wetlands Inventory (1979 imagery)




loss of wetlands – basic steady-state model of drainage



loss of wetlands – observed drainage




What caused weir failure and resulting rapid incision in 2011? --- historically high water



data from the North Dakota State Water Commission

What caused weir failure and resulting rapid incision in 2011? --- a much larger watershed



So what are some of the problems related to the ditch?

1. Reduced forage
2. Lower water table & increased expense for irrigation
3. Downstream sediment transport
4. Repeated reconstruction of bridges and culverts
5. Degraded water quality
6. Disturbed erodible soils and invasive weeds
7. Unknown environmental effect on species diversity and vigor

What were the alternatives?

1. Divert excess water toward the east and south
2. Compensation fund for flood damage (most times dry)
3. Off-channel impoundment, constructed wetlands

Summary --- Observations from Iron Springs Creek

- Problem with "one-size-fits all" for stream management
- Regional stream classification may be essential
- Delineating recharge / capture zones becomes more important than surface watersheds in areas of permeable soils
- Need to regulate diverted water both to and from GWD streams
- Serious hydrological problems may take decades to appear